

Benetech Temp and Humidity Meter GM1362



- Maximum and minimum measurement
- Data hold
- LCD backlit display
- Low battery display
- Auto power off

ME6015- Benetech Model Number GM-1362

| | |
|-----------------|---------------|
| Measuring Range | - 10 to 50 °C |
| Humidity | 5% to 98% RH |
| Power supply | 9V battery |